

10/516783
CEKAttorney's Docket No. 915-006.067**PATENT****IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**Patent Number: **7,353,412**Issued: **April 1, 2008**Name of Patentee: **SPILKER****Title of Invention: ELECTRICAL CIRCUIT FOR CONTROLLING POWER SUPPLY AND MOTOR VEHICLE BUILT-IN DEVICE BEING OPERABLY CONNECTED TO AN EXTERNAL POWER SUPPLY****Commissioner of Patents**

P.O. Box 1450

Alexandria, VA 22313-1450

Certificate**ATTENTION: Decision and Certificate of Correction
Branch of the Patent Issue Division****MAY 13 2008****of Correction****REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR APPLICANT'S MISTAKE (37 CFR 1.323)**

1. It is noted that an error appears in this patent of a

- clerical
- typographical
- minor

nature or character, as more fully described below. It occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination. A certificate of correction is requested.

2. Attached hereto in duplicate is Form PTO-1050 with at least one copy being suitable for printing.

NOTE: Form PTO/SB/44 (also Form PTO-1050), using the column and line number in the printed patent, should be used exclusively regardless of the length or complexity of the subject matter. MPEP § 1485 7th ed.

NOTE: The patent grant should be retained by the patentee. The PTO does not attach the certificate of correction to the patentee's copy of the patent. The patent grant will be returned to the patentee if submitted. MPEP § 1485. 7th ed.

I hereby certify that this correspondence is being deposited today with the United States Postal Service as first class mail in an envelope addressed to: Assistant Commissioner for Patents, U.S. Patent and Trademark Office, PO Box 1450, Alexandria, VA 22313-1450.

Lissette Ramos

5/5/08

Date

RECEIVED-USPTO
(Request for Certificate of Correction of Patent for PTO Mistake) [14-1]-page(s) of (2) publication

3. The exact page and line number where the errors are shown correctly in the application file are:

NOTE: This information should be identified in this request, however, on Form PTO-1050, only the column and line number in the printed patent should be used. MPEP § 1485.

1. Application specification as originally filed at page 3, lines 2-9.

4. Please send the Certificate to:

Name: Alfred Fressola
Ware, Fressola, Van Der Sluys & Adolphson LLP
Address: 755 Main Street, P.O. Box 224
Monroe, Connecticut 06468

5. Please pay the fee required by 37 C.F.R. § 1.20(a)-\$100.00, as follows:

- Attached is a check money order in the amount of \$ 100.00
 Authorization is hereby made to charge the amount of \$ _____
to Deposit Account No. _____
to Credit card as shown on the attached credit card information authorization form PTO-2038.

WARNING: Credit card information should not be included on this form as it may become public.

- Charge any additional fees required by this paper or credit any overpayment in the manner authorized above.
A duplicate of this paper is attached.

Date: May 5, 2008

Reg. No. 27,550

Tel. No.: (203) 261-1234

Customer No.: 004955


ALFRED A. FRESSOLA
WARE, FRESSOLA, VAN DER SLUYS & ADOLPHSON
Bradford Green, Bldg. 5, 755 Main Street
P.O. Box 224
Monroe, CT 06468

NOTE: The certificate of correction for applicant's mistake may be signed by the attorney of record, unlike that for PTO mistake, where the patentee or an owner of an interest in the invention must make the request.

(Request for Certificate of Correction of Patent for Applicant's Mistake) [14-2]-page 2 of 2)

RECEIVED-USPTO
Patent Publication

MAY 13 2008

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : **7,353,412**
DATED : **April 1, 2008**
INVENTOR(S) : **SPILKER**
TITLE : **Electrical Circuit for Controlling Power Supply and Motor Vehicle Built-in Device
Being Operably Connected to an External Power Supply**

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

1. At column 13, line 47, claim 3, line 11, please remove the word "cub-circuit" and replace with --sub-circuit--.

MAILING ADDRESS OF SENDER:

DOCKET # 915-006.067

PATENT NO. **7,353,412**
RECEIVED-USPTO
Patent Publication

Alfred A. Fressola
Ware, Fressola, Van Der Sluys & Adolphson LLP
755 Main Street, P.O. Box 224
Monroe, Connecticut 06468

MAY 13 2008

Burden Hour Statement: This form is estimated to take 1.0 hours to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Commissioner of Patents, PO Box 1450, Alexandria, VA 22313-1450.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,353,412
DATED: : April 1, 2008
INVENTOR(S) : SPILKER
TITLE : Electrical Circuit for Controlling Power Supply and Motor Vehicle Built-in Device
Being Operably Connected to an External Power Supply

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

1. At column 13, line 47, claim 3, line 11, please remove the word "cub-circuit" and replace with --sub-circuit--.

MAILING ADDRESS OF SENDER:

DOCKET # 915-006.067

PATENT NO 7,353,412
RECEIVED-USPTO
Patent Publication

Alfred A. Fressola
Ware, Fressola, Van Der Sluys & Adolphson LLP
755 Main Street, P.O. Box 224
Monroe, Connecticut 06468

MAY 13 2008

Burden Hour Statement: This form is estimated to take 1.0 hours to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Commissioner of Patents, PO Box 1450, Alexandria, VA 22313-1450.